



Part no	Description
16 80 15	Speedglas 9100 sweatband (pk=3)
16 90 05	Speedglas 9100 head protection, black TecaWeld
16 90 10	Speedglas 9100 neck protection, black TecaWeld
16 91 00	Head cape, black/grey TecaWeld
17 10 20	Magnifying Lens 1.0
17 10 21	Magnifying Lens 1.5
17 10 22	Magnifying Lens 2.0
17 10 23	Magnifying Lens 2.5
42 20 00	Battery (pk=2)
50 00 05	Speedglas 9100V auto darkening welding lens 5, 8/9-13
50 00 15	Speedglas 9100X auto darkening welding lens 5, 8/9-13

Part no	Description
50 00 25	Speedglas 9100XX auto darkening welding lens 5, 8/9-13
50 11 90	Speedglas 9100 shield without head harness
50 18 90	Speedglas 9100 SW shield without head harness
52 60 00	Speedglas 9100 outer protection plate standard 147°C (pk=10)
52 70 00	Speedglas 9100 outer protection plate hard coated 147°C (pk=10)
52 70 70	Speedglas 9100 outer protection plate heat 202°C (pk=10)
52 80 05	Speedglas 9100V inner protection plate (pk=5) marked, 117x50 cm
52 80 15	Speedglas 9100X inner protection plate (pk=5) marked, 117x61 cm

Part no	Description
52 80 25	Speedglas 9100XX inner protection plate (pk=5) marked, 117x77 cm
53 10 00	Speedglas 9100 battery holder (pk=2)
53 20 00	Speedglas 9100 silver front
53 20 15	SideWindows cover plate (sticker), 5 pairs
53 30 00	Speedglas 9100 head harness including assembly parts
53 60 00	Speedglas 9100 pivot mechanism, left and right for head harness
53 61 00	Speedglas 9100 head harness front part
53 62 00	Speedglas 9100 head harness back part